

Inductive, photoelectric and area sensors with ATEX Category 3 certification could be used in presence of explosive atmospheres caused by gas and powder. Which are their applications?

Filling bags packaging machine (chemicals, flours, corn and seeds, fertilizer), painting system (wood, metal, glass) and mills. BX area sensors are available either with ATEX Category 2 certification.

MD. Sensors serving industrial automation.



www.microdetectors.com